





# FENJA 2




1	1X	1/2
2	1X	1/2
3	1X	1/2
4	2X	1/2
5	1X	1/2
6	1X	2/2
7	2X	2/2

<b>A</b>	M6*20	<b>B</b>	M6*15	<b>C</b>	M7*50	<b>D</b>	Ø8*30	<b>E</b>	M4*14	<b>F1</b>	<b>F2</b>		
	16X		24X		8X		4X		16X		4X		4X
<b>G</b>	Ø16*6.5*1.5	<b>H</b>	Ø32*M6*25	<b>I</b>	Ø25	<b>J</b>	M4	<b>K</b>		<b>L</b>	Ø22*8*2		
	40X		4X		4X		1X		1X		4X		


# I.

## 1.




E	M4*14	16X
F1		4X
F2		4X


## 2.



B	M6*15	16X
G	Ø16*Ø6.5*1.5	16X
J	M4	1X
L	Ø22*Ø8*2	4X




## 3.



C	M7*50	8X
D	Ø8*30	4X
J	M4	1X
K		1X


11.

4.




A	M6*20		8X
G	Ø16*Ø6.5*1.5		8X
J	M4		1X

5.



A	M6*20		8X
B	M6*15		8X
G	Ø16*Ø6.5*1.5		16X
J	M4		1X



6.




H	Ø32*M6*25		4X
I	Ø25		4X

III.


7.



8.




9.



IV.

10.



11.

