



S510 510 ASSEMBLY INSTRUCTION


1 x1



2 x1



Ax8




Bx6




3 x4




4 x2



5 x1




Cx2




Dx1




STEP 1



STEP 2



STEP 3



STEP 4

