

Montageanleitung

Assembly instruction

Instructions de montage

Instrucciones de montaje

Istruzioni per il montaggio

Руководство по монтажу

Instrukcja montażu

Montážní návod

Návod na montáž

Szerelési utasítás

Инструкция за монтаж

Kurulum Talimatları

Navodilo za montažo

Montagehandleiding

A s e n n u s o h j e

Upute o montaži

Instrucțiuni de montaj

Monteringsveiledning


إرشادات التركيب

Monteringsvejledning

Instruções de montagem


Monteringsanvisning

Beschläge / fittings / Ferrures pour meubles / Herrajes / Guarnizioni / Крепления / Okucia / Kování / Kovanie / Vasalások / обков / Parçaları / okovje / Hang- en sluitwerk / helat / Oblo-ge / armături, balamale / Beslag / بعض التركيبات / Beslag / Guarnições / Beslag





Sie benötigen:
You need:
Vous avez besoin de:
Necesita:
Le servono :
Вам потребуются:
Potrebujete:
Tarvitset:
Aveți nevoie de :
Du behøver:
سوف تحتاج إلى:

Potrzebne są:
Potřebujete:
Potrebujete:
Szőkséges eszközök:
На Вас са Ви нужни:
Ihtiyaciniz:
U hebt nodig:
Trebate:
Du skal bruge:
Necessita de:
Du behöver:





BRISTOL 1000

Art.-Nr. 4020-1000



BRISTOL 1000

Teile / article / Pièces / Piezas / Pezzi / части / Części / Díly / Diely / Alkatrészek / Детали / parçalar / dele / Onderdelen / osat / Dijelovi
piese / Deler / والتجهيزات / Dele / Peças / Delar



BRISTOL 1000


B

4,0x30
4 x SR 3

2 x GR34


ZB1

1




2

2x



3

2x






180°



4

2x



180°




90°






5

2x




BRISTOL 1000


C

 15x9 4 x ZB12	 280 2 x SK4	 6,3x19 4 x SO 19	 6 x VB1	 5,0x35 8 x VB4
--	--	--	--	--


1







2




3




D



1






2




BRISTOL 1000


E




1



2




3




F




ZB1



4 x TB14




2 x VB1




5,0x35
9 x VB4


1



2







3




BRISTOL 1000


G




1 2x




2 2x




3



H

 1 x GR34	 4,0x30 2 x SR 3	 2 x TB9	 3,5x15 4 x SP1
--	---	---	--



I




5 x WI 2




3,5x15
10 x SP 1

1




2




180°


J



1




2



BRISTOL 1000



K

6 x AK1




6x

1



2



3



L







BRISTOL 1000

M


50 x SO3







3,5x30
10 x SP 11


5 x
GL1




BRISTOL 1000


N



1





2




BRISTOL 1000


O



2 x ZB16




5 x VB10



5 x VB9








6 x SP1



P

3,5x15
4 x SP1

M4x8
4 x SG1



R

6 x AK3

