






Tina 1




1

2

3



R




L

1	1 x
2	1 x
3	1 x



1/1

A	M6X45	B	M6x13	C	Ø14xØ6x1.5	D	4MM	E	T2.0x90x90
	4x		4x		4x		1x		1x

I.

1

A M6x45
2x

C Ø14xØ6x1.5
2x

D 4MM
1x

75%

2

A M6x45
2x

C Ø14xØ6x1.5
2x

D 4MM
1x

75%

3

B M6x13
4x

D 4MM
1x

E T2.0x90x90
1x

75%

4

D 4MM
1x

100%