






5101709/00



		
1	1X	1/1
2	1X	1/1
3	3X	1/1
4	1X	1/1
5	1X	1/1
6	1X	1/1
7	3X	1/1
8	1X	1/1



1/1

A

M6X14

B


Ø20

C

5MM

D


Ø16



24x



10x




1x



9x


I.

1



A	M6x14
	12x
C	5MM
	1x
D	Ø16
	4x
100%	



2





A	M6x14
	12x
C	5MM
	1x
D	Ø16
	5x
100%	

II.

3




4





5




B






Ø20

6x



6



LE TRI
+ FACILE



Séparez les éléments avant de trier