











A





B




A  Ax8	B  Bx32 M6x20	C  Cx1 4	D  Dx2
E  Ex2			






2a

A  Ax4	B  Bx16 M6x20	D  Dx1	E  Ex1 Plastic
---	--	--	---






2b




A  Ax4	B  Bx16 M6x20	D  Dx1	E  Ex1 Plastic
---	--	--	---





3a



3b





Attention!

