







P 167





2.1



2.2



3




1	1X	1/2
2.1/2.2	4X	2/2
3	2X	2/2

	A 	B 	C 	D 	E
F 	G 	H 	I 	J 	

I.

1.




A



M6x12


6x

I




6MM

1x



2.



G


Ø18xØ6x3



4x


C

M6x35




6x

H




5MM


1x




II.


3.



B	M8x12
	
J	16x 8MM
	
	1x 

4.1 → 2.1



D	M8x16
	
E	16x Ø18xØ8x1.5
	
H	16X 5MM
	
	1x 

